



COLUMBIA UNIVERSITY
Environmental Health & Safety
www.ehs.columbia.edu

Radiation Safety Program

Medical Center - T: 212-305-0303 F: 212-305-0318
rsocumc@columbia.edu

Morningside - T: 212-854-8749 F: 212-316-4937
rso-ehrs@columbia.edu

Environmental Health & Safety Radiation Safety Program

Attention supervisors and responsible investigators:

Everyone in your department receiving a dosimetry badge needs to take the RASCAL test online. Everyone taking this test should have already attended the radiation safety lecture training. *Annual refresher trainings are required.*

An activated UNI is required to login to RASCAL. If you do not know your UNI, search for your name in the [Columbia Directory](#). Click on your name to view your UNI. Once you have [activated your UNI](#), you are ready to take the test.

How to take online test and get the rascal certificate

- Go to the [RASCAL](#) website
- On the left hand side, under login, choose “Training Center”
- Login using your UNI
- Choose “Course Listings”
- Choose “TC0004 - X-ray Fluorosocopic Users Credentialing course”
- On the left hand side of the screen, choose “Take Test”
- Once the test is complete, e-mail badges@columbia.edu with your name and the subject line “I have completed my radiation safety RASCAL training”

View our [training schedule](#) for lecture training dates.

If you have problems with the RASCAL system, contact them directly:
E-mail rascal@columbia.edu or call the help line at (212) 851-0213